



TWO HY-WAY 12,000-GALLON TACK TANKS RAP-16133

SKU: RAP-16133

Condition: Used

Region: East

Mobility: Stationary

Size (Nominal): 12,000 Gallon

EQ Type: Tank

SKU: RAP-16133



PRODUCT DESCRIPTION

- HyWay Electric Tack Tank 1
 - Equipment Id number 8109. Closest to old baghouse. Previously held trackless tack, Newer electrical panel.
 - Tank is empty. There is a flat plate covering the electric elements. In the pictures it looks like it is material above the elements
 - HyWay Model - 12ES sn K00784-631
 - 12,000 Gallon capacity single compartment
 - 6 electric elements estimated 20KW each
 - 2013 Temp controllers
 - 7.5hp 3" pump system with breaker mounted on stand
 - Tank sits on 10' high stand. Bolted together. Can be dismantled for shipping
 - Tank thickness at the bottom .247.
 - Tank shipping 10'10" wide x 11'6" high x 28' long
 - Piping, pump, ladders and catwalk need removed for transport. As well as the stand dismantled if chosen to take with the tank.
 - Ladder access to ground
 - Skin and insulation intact and no visible imperfections. Interior of tank does not appear to show any deterioration
-
- HyWay LecTank Electric Tack Tank 2
 - Equipment ID number 8108. Older tank, closer to Astec baghouse. Previously held SS1 tack. Older electrical panel.
 - Tank is empty. There is a flat plate covering the electric elements. In the pictures it looks like it is material above the elements.
 - Model 12ES sn 605
 - 12,000 gallon single compartment
 - 5 elements 20KW each 240volt
 - Stansteel temp controller as well as 2012 temp display on panel
 - 7.5hp 3" pump system w/ breaker mounted on stand
 - Tank shipping 10'10" wide x 11'6" high x 28' long
 - Tank sits on stand 10'. Stand is welded together
 - Stand shipping 10'4" high x 8'8" wide x 18' long
 - Piping, pump, catwalks need removed for transport. Stand ships as it is if chosen to take with the tank.
 - There is not a ladder to the ground.
 - Skin and insulation intact and no visible imperfections. Interior of tank does not appear to show any signs of deterioration.
 - Some very minimal buildup on sidewalls